

I, MICHAEL P. GRIFFIN, certify that under my direction and supervision this map was drawn from an actual field survey; that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.


Witness my hand and seal this 5TH day of MAY 2020.



22' SLOPE, DRAINAGE & UTILITY EASEMENT

JOSEPH K. REVELS
 PIN #0644-25-8924.000
 D.B. 2298 PG. 255
 MAP #2004-389

BK 2019 PGS 421-424
 HARNETT CO. REGISTRY




SETBACKS

FRONT	35'
REAR	25'
SIDE	10'
CORNER SIDE	20'

C1 R=250.00' L=240.54' N28°01'49"W 231.37'
 C2 R=300.00' L=184.13' S18°02'58"E 181.25'

LEGEND

EIP	EXISTING IRON PIPE	FES	FLARED END SECTION
IPS	IRON PIPE SET	WM	WATER METER
RW	RIGHT OF WAY	CO	CLEAN OUT
N/F	NOW OR FORMERLY	FH	FIRE HYDRANT
EIS	EXISTING IRON STAKE	CB	CATCH BASIN



THIS PROPERTY IS NOT LOCATED
 IN THE 100 YEAR FLOOD ZONE.

GLS GRIFFIN LAND SURVEYING, INC.
 P.O. BOX 148
 FUQUAY-VARINA, NC 27526
 (919) - 567 - 1963

FOUNDATION SURVEY
 FOR
DAN RYAN BUILDERS
OLDE MILL VILLAGE
LOT 1
 VILLAGE BEND DRIVE
 NORTH CAROLINA
 HARNETT CO. HECTOR'S CREEK TWSHP

DRAWN BY KDF	DATE 5/5/20
CHECKED BY MPG	SCALE 1" = 60'