HTE# 5F52	## Harnett County Department of Public Health	7.0
PERMIT #	Operation Permit 2577	
System Installer: Basement with plun Type of Water Supp	New Installation Septic Tank Nitrification Line Repair PROPERTY LOCATION: 30,1215 Respectively.    New Installation   Septic Tank   Nitrification Line   Repair	
This system has been ins	stalled in compliance with applicable North Carolina General Statutes, Rules for Sewage Treatment and Disposal, and all conditions of the Improvement Permit and Construction Authoriz.	ation.
	10°- 50°0 red Reper 10°- 10° 10° 10° 10° 10° 10° 10° 10° 10° 10°	
PERMIT CONDITIONS:	SA 1215 Rosser Pottman Pad	
I. Performance: II. Monitoring: III. Maintenance:	System shall perform in accordance with Rule .1961.  As required by Rule .1961. Other:  Subsurface system operator required? Yes  No  If yes, see attached sheet for additional operation conditions, maintenance and reporting.	· Can
IV. Operation:		
V. Other:		
	D-Box	PWR Line
Following are the spe Type of system: Subsurface Drainage Field French Drain Required	Conventional Other Conventional	gallons
	1 - 2045	

8-13-20

Date

Authorized State Agent