


I, MICHAEL P. GRIFFIN, certify that under my direction and supervision this map was drawn from an actual field survey; that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this 30TH day of DECEMBER 2020.

BK 2006 PG 477.478  
HARNETT CO. REGISTRY



SIERRA VILLA  
SECTION NINE  
RIGHT OF WAY  
PC F SLIDE 226-B




NORTH DAKOTA COURT  
50' PUBLIC RW

SETBACKS


FRONT	35'
REAR	25'
SIDE	10'
CORNER SIDE	20'

LEGEND

EIP	EXISTING IRON PIPE	FES	FLARED END SECTION
IPS	IRON PIPE SET	WM	WATER METER
RW	RIGHT OF WAY	CO	CLEAN OUT
N/F	NOW OR FORMERLY	FH	FIRE HYDRANT
EIS	EXISTING IRON STAKE	CB	CATCH BASIN



THIS PROPERTY IS NOT LOCATED  
IN THE 100 YEAR FLOOD ZONE.



GRIFFIN LAND SURVEYING, INC.

P. O. BOX 148  
FUQUAY-VARINA, NC 27526  
(919) - 567 - 1963

FOUNDATION SURVEY

FOR  
A & G RESIDENTIAL

SIERRA VILLAGE  
AT OVERHILLS

LOT 4

NORTH DAKOTA COURT

NORTH CAROLINA

HARNETT CO. ANDERSON CREEK TWSHP

DRAWN BY NMF

DATE 12/30/20

CHECKED BY MPG

SCALE 1" = 30'