



Builders First Source 23 Red Cedar Way Apex, NC 27523 Phone: (919) 363-4956 Fax: (919) 387-8565 https://www.bldr.com

General Notes:
- Per ANSI/TPI 1-2002 all " Truss to Wall" connections are the responsibility of the Building

- Designer, not the Truss Manufacturer.

 Dimensions are Feet-Inches- Sixteenths.

 Trusses are to be 24" o.c. unless noted otherwise
- Trusses are not designed to support brick U.N.O.
- Do not cut or modify trusses without first contacting Builders FirstSource.
 Immediately contact Builders FirstSource if

trusses are damaged. Connection Notes:

- Connection Notes:

 All hangers are to be Simpson or equivalent U.N.O.

 Use Manufacturer's specifications for all hanger connections U.N.O.


 Use 10d x 1 1/2" Nails in hanger connections to single
- ply roof girder trusses.

Floor notes:
- Shift truss as required to avoid plumbing traps.
- Installation Contractor and/or Field Supervisor are to verify all dimensions, trap locations, and options prior to

Dimension Notes:

- Drawing not to scale. Do not scale dimensions

 \triangle \triangleleft ∇ \triangleright LEFT END OF TRUSS AS SHOWN ON TRUSS DETAIL DRAWINGS ARE INDICATED BY TRIANGLE ICONS.



HANGER LIST ALL TIE DOWNS H2.5A UNLESS NOTED

	A422	JL	SPECIAL ITEMS LIST				
	JS410	Hj [10					
1 HH	US46	HJ [6					
			MISC MATERIAL				
MCKEE							
NELSON III			Е	LEV:	EURO		
ANDERSON CREEK ACADEMY							
	NC		-	LOT:	1076		
			APPWRIGHT #				
• [FLOOR]							
• []			0	CODE:		IRC 2015	
• []			LOADING:				
			Т	.C.L.L.		40 PSF	
DESIGNED B	v: M	MTJ		.C.D.L.	10 PSF		
LAYOUT:	EUR	EURO		.C.L.L.	0 PSF		
L/O DATE:	2/15/2021		В	.C.D.L.	5 PSF		
REVISION HISTORY		WIND:					
REV1:	XX/XX/XX		١	М.Р.Н.		115 MPH	
REV2:	XX/XX	(X/XX/XX		EXPOSURE CATEGORY			
REV3: XX/XX/XX		B (WOODED AREAS/OTHERS)					
PICK TICKE	T:		JOB N		0:		
SALES N	0:			ACCT NO:			
HATC							

ATTIC ROOM

OLUME CEILIN STICK FRAMING