

T 980 210-3312

104 Avon Street, Monroe, North Carolina 28110 www.tyndallengineering.com

October 14, 2021

Ben Stout Construction 1790 Metro Medical Dr. Fayetteville, NC

Ph: 910-779-0019

Email: billing@benstoutconstruction.com

Reference: Engineering Services

Lot 29 Forest Ridge Subdivision

(192 Tanna Pl.) Cameron, NC

Project No.: 2102-020198

To Whom it may concern:

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) was onsite October 13, 2021 to observe the following item(s):

1) Rear porch bed-joint in excess of 1-1/2" in thickness.

The following conclusions and recommendations were noted:

1) The existing bed-joint was noted as being 2" in thickness at its thickest portion. Based on our visual observations and analysis, the existing mortar joint was noted as being adequate and has not undermined the structural integrity of the porch foundation. No action recommended.

We appreciate the opportunity able to assist you during this phase of the project. Should you require further assistance or additional information, please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design

Lloyd W. Jones

Prentice Tyndall Jr., P.E.





