

Southeastern Soil & Environmental Associates, Inc. P.O. Box 9321 Fayetteville, NC 28311 Phone/Fax (910) 822-4540 Email mike@southeasternsoil.com



SOIL/SITE EVALUATION • SOIL PHYSICAL ANALYSIS • LAND USE/SUBDIVISION PLANNING • WETLANDS GROUNDWATER DRAINAGE/MOUNDING • SURFACE/SUBSURFACE WASTE TREATMENT SYSTEMS, EVALUATION & DESIGN

SOUTHEASTERN SOIL & ENVIRONMENTAL ASSOC., INC.

PROPOSED SUBSURFACE WASTE DISPOSAL SYSTEM DETAIL SHEET

	SUBDIVISION:	MORGAN FARMS A	PORTH	LOT 54
	INITIAL SYSTEM: APPROVED 25% REDUCTION			REPAIR APPRIVED 25% REDUCTION
	DISTRIBUTION:	SEPIAL	 ,	DISTRIBUTION SEPIAL
	BENCHMARK:	100.0		LOCATION PC SY/ST
	NO. BEDROOMS	: 4	•	LTAR 0.35 GPD/FTL
	LINE FL	AG COLOR	ELEVATION	LENGTH
2		Ý	103.50	751
13.)		103.34	75'
ritue {	3	<u>Y</u>	103,17	3/1
suster /	-	- ρ	103.08	75'
9' (Y	102.84	75'
				375'
	6	ρ	102.67	75.
	7	У	102.50	2-1
	8	ρ	102.08	フン´′
	<u> </u>	У	101.67	25-1
		ρ	100,58	75
				325'
	BY MEAKE	2		DATE PECSUBER 2019/JAN 2020
	TYPICAL PROFILE			
				THERE SHALL BE NO GRADING,
	14-36+ 9CL/SC (F: 064) 			CUTTING, LOGGING OR OTHER SOIL
				DISTURBANCE IN SEPTIC AREA
	Cr 2/PA	a > 28"		HEALTH DEPARTMENT USE ONLY.
	INSTAU	AT 16", ADD 2"	Coven	DESIGNS DO NOT GURANTEE FUNCTIONALITY