



## LAND SURVEYING, INC.

P. O. B O X 1 4 8 F U Q U A Y - V A R I N A , N C 27526 (9 1 9) - 5 6 7 - 1 9 6 3

DRAWN BY <b>NMF</b>	DATE 7/6/21
CHECKED <u>BY</u> MPG	SCAL <u>E</u> 1" = 40'


FOR

D.R. HORTON

MORGAN NORTH **LOT 36** 

256 SIMPLY COUNTRY LANE NORTH CAROLINA HARNETT CO. HECTOR'S CREEK TWSHP

## Southeastern Soil & Environmental Associates, Inc.



1 "=1001

 ${\tt SOUTHEASTERN\ SOIL\ \&\ ENVIRONMENTAL\ ASSOC.,\ INC.}$ 

## PROPOSED SUBSURFACE WASTE DISPOSAL SYSTEM DETAIL SHEET

	SUBDIVISION: MORGAN FAMS NORTH  PUMP TO  INITIAL SYSTEM: APPROVED 25% REDUCTION  DISTRIBUTION: D-ROX			REPAIR APPRIVED 251. REDUCTION		
	BENCHMARK:		DISTRIBUTION D-Box  LOCATION P- 35/36			
	NO. BEDROOMS:	3			.3 GPD/FT2	
	LINE FLAC	G COLOR	ELEVATION		<u>LENGTH</u>	
_	<u>Z</u> '	$\omega$	97.42		ンプ	<del>_</del>
Initial system	$\frac{1}{2}$	P	97.42		25'	<del></del>
	/ 1	W P	97.42		75'	_
01-	<u>U 7</u>	<u> </u>	97.17		25-/	
					300'	<b></b>
	5	W	97.00		75'	
		P	96.75		75-1	
		W	96.34	***	25'	-
	8	P	95.92		75'	
					300'	<del>-</del>
						_
				,		<del>-</del>
BY MEAKER				DATE PECE	MBER 2019/JAN	- 2020
	TYPICAL PROFILE			THERE SHALL BE NO GRADING,  CUTTING, LOGGING OR OTHER SOIL  DISTURBANCE IN SEPTIC AREA		-
	0-10 65 (					
	10-36+ SCC (F:, 16/1)					
	(N)TAN AT 18"			HEALTH DEPARTMENT USE ONLY.		
				DESIGNS DO NOT GURANTEE FUNCTIONALITY		