

System: Gravity to Serial Dist. Lines: 2-4 (282')


Accepted Status System

0.35 Soil LTAR

Repair: Gravity Serial Dist. Lines: 1 & 5-7 (203')

T&J Panel 0.35 Soil LTAR







Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

3-Bedroom Septic Layout Lot 100, Birchwood Subdivision Harnett County, North Carolina Job# : 3753

Drawn By : MB

Date : 09/22/2021

Revision: 4/05/2022