
System: HHHHHH Repair: ----

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.



System: Gravity to Serial Dist. Lines: 5—7, (345') Accepted Status System


0.35 Soil LTAR 18" Trench Bottom

Repair: Gravity to Serial Dist.

Lines: 1-4,8, (385')

Accepted Status System

0.35 Soil LTAR 18" Trench Bottom





Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

3—Bedroom Septic Layout Lot 79, Birchwood Subdivision Harnett County, North Carolina Job#: 3753

Drawn By: LW

Date: 07/02/2021

Revision: