




System: 
 Repair: 

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.

System: Gravity Serial Dist.
 Lines: 1-4a, (235')
 T&J Panel 50% Reduction
 0.35 Soil LTAR

Repair: Pressure Manifold
 Lines: 4b-7, (230')
 T&J Panel 50% Reduction
 0.35 Soil LTAR



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

5-Bedroom Septic Layout
 96 gal/bedroom/day flow reduction
 Lot 5, Birchwood Subdivision
 Harnett County, North Carolina

Job# : 3753
Drawn By : LW
Date : 10/11/2021
Revision: 6/13/2022