



I, MICHAEL P. GRIFFIN, certify that under my direction and supervision this map was drawn from an actual field survey; that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this 16TH day of JUNE 2022.



(61)
(62)



BK 2022 PGS 132-133
HARNETT CO. REGISTRY

TIMBER SKIP DRIVE
50' PRIVATE RW

SETBACKS


FRONT	35'
REAR	25'
SIDE	5'
OTHER SIDE	10'

C1 R=125.00' L=171.39' N47°51'11"W 158.28'

THIS PROPERTY IS NOT LOCATED IN THE 100 YEAR FLOOD ZONE.

LEGEND

EIP	EXISTING IRON PIPE	FES	FLARED END SECTION
IPS	IRON PIPE SET	WM	WATER METER
RW	RIGHT OF WAY	CO	CLEAN OUT
N/F	NOW OR FORMERLY	FH	FIRE HYDRANT
EIS	EXISTING IRON STAKE	CB	CATCH BASIN



GRiffin LAND SURVEYING, INC.
 P.O. BOX 148
 FUQUAY-VARINA, NC 27526
 (919) - 567 - 1963

FOUNDATION SURVEY
 FOR
H & H HOMES
ANDERSON CREEK CLUB
LOT 60
 TIMBER SKIP DRIVE
 NORTH CAROLINA
 HARNETT COUNTY ANDERSON CREEK TOWNSHIP

DRAWN BY KDF

DATE 6/16/22

CHECKED BY MPG

SCALE 1" = 30'