
I, MICHAEL P. GRIFFIN , certify that under my direction and supervision this map was drawn from an actual field survey; that the error of clasure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this day of MONTH 2022.



OPEN SPACE



IMPERVIOUS AREAS

HOUSE DRIVE # WALKS PATIO	1708 448 120	50	FT.
TOTAL	2276		

SETBACKS

FRONT	20
REAR	15
SIDE	10
CORNER SIDE	15

PRELIMINARY

NOT FOR RECORDATION, SALES OR CONVEYANCE LEGEND FES WM

EIP IPS R/W N/F EIS EXISTING IRON PIPE IRON PIPE SET RIGHT OF WAY NOW OR FORMERLY FLARED END SECTION WATER METER CLEAN OUT FIRE HYDRANT CO EXISTING IRON STAKE CATCH BASIN





GRIFFIN LAND SURVEYING, INC.

P. O. B O X 1 4 8 FUQUAY-VARINA, NC 27526 (9 1 9) - 5 6 7 - 1 9 6 3

DRAWN BY NMF	DATE 4/14/22
CHECKED BY MPG	SCALE 1" = 30'

PLOT PLAN FOR

D. R. HORTON

WOODGROVE

LOT 5

SILVER MAPLE DRIVE NORTH CAROLINA HARNETT CO. HECTOR'S CREEK TWSHP