
I, MICHAEL P. GRIFFIN , certify that under my direction and supervision this map was drawn from an actual field survey, that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this day of MONTH 2022.





WINTERBERRY WAY 50' PUBLIC RW # UTILITY

IMPERVIOUS AREAS

HOUSE 1708 SQ. FT.
DRIVE \$ WALKS 448 SQ. FT.
PATIO 120 SQ. FT.
TOTAL 2276 SQ. FT.

SETBACKS

 FRONT
 20'

 REAR
 1.5'

 SIDE
 1.0'


 CORNER SIDE
 1.5'

PRELIMINARY

NOT FOR RECORDATION, SALES OR CONVEYANCE

LEGEND

EXISTING IRON PIPE IRON PIPE SET RIGHT OF WAY NOW OR FORMERLY FES FLARED END SECTION
WM WATER METER
CO CLEAN OUT
FH FIRE HYDRANT
CB CATCH BASIN



GRIFFIN LAND SURVEYING, INC.

EIP

IPS

R/W

N/F

P. O. B O X 1 4 8 F U Q U A Y - V A R I N A , N C 2 7 5 2 6 (9 1 9) - 5 6 7 - 1 9 6 3

DRAWN BY NMF DATE 5/13/22

CHECKED BY MPG SCALE 1" = 30'

PLOT PLAN

D. R. HORTON

WOODGROVE

LOT 40

WINTERBERRY WAY

NORTH CAROLINA

HARNETT CO. HECTOR'S CREEK TWSHP