



I, MICHAEL P. GRIFFIN, certify that under my direction and supervision this map was drawn from an actual field survey; that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this 16TH day of JANUARY 2023.



BM 2022 FOS-341-244  
HARNETT CO. REGISTRY



SOLOMON DRIVE  
50' R/W (PUBLIC & UTILITY ACCESS)

SETBACKS



FRONT	35'
REAR	25'
SIDE	10'
CORNER SIDE	20'

C1 R=1975.00' L=100.08' N36°14'54"E 100.07'

THIS PROPERTY IS NOT LOCATED  
IN THE 100 YEAR FLOOD ZONE.

LEGEND

EIP	EXISTING IRON PIPE	FES	FLARED END SECTION
IPS	IRON PIPE SET	WM	WATER METER
R/W	RIGHT OF WAY	CO	CLEAN OUT
N/F	NOW OR FORMERLY	FH	FIRE HYDRANT
EIS	EXISTING IRON STAKE	CB	CATCH BASIN



GRIFFIN LAND SURVEYING, INC.

P. O. BOX 148  
FUQUAY-VARINA, NC 27526  
(919) - 567-1963

FOUNDATION SURVEY  
FOR

**BEN STOUT  
CONSTRUCTION**  
LIBERTY MEADOWS

**LOT 6**  
SOLOMON DRIVE  
PINEVIEW, N.C.

HARNETT COUNTY JOHNSONVILLE TOWNSHIP

DRAWN BY MPG

DATE 1/16/23

CHECKED BY MPG

SCALE 1" = 40'