





System: 
 Repair: 

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.

System: Gravity to Serial Dist.
 Lines: 1-5, (350')
 Accepted Status System
 0.35 Soil LTAR

Repair: Pressure Manifold
 Lines: 4-6, (232')
 T&J Panel 50% Reduction
 0.35 Soil LTAR



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout
 Lot 126, Birchwood Subdivision
 Harnett County, North Carolina

| |
|------------------|
| Job# : 3753 |
| Drawn By : LW |
| Date : 7/25/2022 |
| Revision: |
| |
| |