

System: Gravity to Serial Dist.


Lines: 1-5, (365') Accepted Status System

0.5 Soil LTAR

Repair: Gravity to Serial Dist.

Lines: 4-6, (350') Accepted Status System

0.5 Soil LTAR





Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout Lot 121, Birchwood Subdivision Harnett County, North Carolina

Job# : 3753 Drawn By : LW Date: 7/25/2022 Revision: