

Howerton Services, PLLC
License # P-1716
3513 Cathedral Bell Road
Raleigh, NC 27614
(919) 270-3460

June 5, 2023

Subject: 505 Lambert Lane
Fuquay Varina, NC 27526
Framing Modification Letter
Harnett County Permit #: SFD2303-0060

Based on the request of the Contractor, the beam in the ceiling of the 2nd floor left bedroom was modified. My assessment and recommendations are as follows:

- The proposed triple 2x10 beam in the ceiling of the 2nd floor left side bedroom was modified to a double 1 ¾"x 14" LVL beam. The modification to a double 14" LVL is acceptable.

The new double 14" LVL beam meets all the requirements of the 2018 North Carolina Building Code for Residences.



06 05 2023