

Client: Project: Address: Jay Norris

71 knight Rd.


Date: 6/1/2023

Input by:

Job Name: J0423-1877 Beams Project #: J0423-1877 Beams

1.750" X 14.000" 2-Ply - PASSED **Kerto-S LVL GDH**

Level: Level



Member Info	rmation			Rea	ctions UNP	ATTERN	NED lb (Uplift)			
Type:	Girder	Application:	Floor	Brg	Direction	Live	Dead	Snow	Wind	Const
Plies:	2	Design Method:	ASD	1	Vertical	3073	3207	0	0	0
Moisture Condition	on: Dry	Building Code:	IBC/IRC 2015	2	Vertical	3073	3207	0	0	0
Deflection LL:	480	Load Sharing:	No							
Deflection TL:	240	Deck:	Not Checked							
Importance:	Normal - II									
Temperature:	Temp <= 100°F									
				Bea	rings					
				Bea	aring Length	Dir.	Cap. React D/L	b Total	Ld. Case	Ld. Comb.
				1 -	SPF 38.000"	Vert	11% 3207 / 307	3 6280	L	D+L
	•.			2 -	SPF 38.000"	Vert	11% 3207 / 307	3 6280	L	D+L

Analysis Results

•						
Analysis	Actual	Location	Allowed	Capacity	Comb.	Case
Moment	21562 ft-lb	12'3 1/2"	26999 ft-lb	0.799 (80%)	D+L	L
Unbraced	21562 ft-lb	12'3 1/2"	21588 ft-lb	0.999 (100%)	D+L	L
Shear	4079 lb	4'4"	10453 lb	0.390 (39%)	D+L	L
LL Defl inch	0.425 (L/518)	12'3 9/16"	0.459 (L/480)	0.926 (93%)	L	L
TL Defl inch	0.869 (L/254)	12'3 9/16"	0.919 (L/240)	0.946 (95%)	D+L	L

Design Notes

- 1 Provide support to prevent lateral movement and rotation at the end bearings. Lateral support may also be required at the interior bearings by the building code.
- 2 Girders are designed to be supported on the bottom edge only.
- 3 Multiple plies must be fastened together as per manufacturer's details.
- 4 Top loads must be supported equally by all plies.
- 5 Top must be laterally braced at a maximum of 4'2 3/8" o.c.
- 6 Bottom must be laterally braced at end bearings.
- 7 Lateral slenderness ratio based on single ply width.

ID	Load Type	Location	Trib Width	Side	Dead 0.9	Live 1	Snow 1.15	Wind 1.6	Const. 1.25	Comments
1	Uniform			Тор	250 PLF	250 PLF	0 PLF	0 PLF	0 PLF	C1GE
	Self Weight				11 PLF					

Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

Dry service conditions, unless noted otherwise
 LVL not to be treated with fire retardant or corrosive

Handling & Installation

IARIGUING & INSTALLATION

LVL beams must not be cut or drilled

Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beams trength values, and code approvals

Damaged Beams must not be used

Design assumes top edge is laterally restrained.

Provide lateral support at bearing points to avoid lateral displacement and rotation

6. For flat roofs provide proper drainage to prevent ponding

This design is valid until 11/3/2024

Metsä Wood 301 Merritt 7 Building, 2nd Floor Norwalk, CT 06851 (800) 622-5850 www.metsawood.com/us

Manufacturer Info

Comtech Comecn Reilly Road Industrial Park P.O. Box 40408, NO USA 28309 910-864-8787

Page 1 of 3







Client: Project: Address: Jay Norris

71 knight Rd.


Date: Input by:

> Job Name: J0423-1877 Beams J0423-1877 Beams

6/1/2023

2-Ply - PASSED 1.750" X 14.000" **Kerto-S LVL** DB₁

Project #: _evel: Level



Member Info	rmation			Rea	ctions UNP	ATTERI	NED II	b (Uplift)			
Type:	Girder	Application:	Floor	Brg	Direction	Live)	Dead	Snow	Wind	Const
Plies:	2	Design Method:	ASD	1	Vertical	428	3	223	0	0	0
Moisture Condition	on: Dry	Building Code:	IBC/IRC 2015	2	Vertical	428	3	223	0	0	0
Deflection LL:	480	Load Sharing:	No								
Deflection TL:	240	Deck:	Not Checked								
Importance:	Normal - II										
Temperature:	Temp <= 100°F										
				Bea	rings						
				Bea	aring Length	Dir.	Сар.	React D/L lb	Total	Ld. Case	Ld. Comb.
				1 -	SPF 3.500"	Vert	12%	223 / 428	651	L	D+L
					CDE 3 500"	Vort	120/	222 / 429	651	1	D±I

Analysis Results

Analysis	Actual	Location	Allowed	Capacity	Comb.	Case
Moment	3330 ft-lb	10'8 1/4"	26999 ft-lb	0.123 (12%)	D+L	L
Unbraced	3330 ft-lb	10'8 1/4"	5646 ft-lb	0.590 (59%)	D+L	L
Shear	575 lb	1'5 1/2"	10453 lb	0.055 (5%)	D+L	L
LL Defl inch	0.113 (L/2226)	10'8 5/16"	0.523 (L/480)	0.216 (22%)	L	L
TL Defl inch	0.172 (L/1462)	10'8 5/16"	1.046 (L/240)	0.164 (16%)	D+L	L

Design Notes

- 1 Provide support to prevent lateral movement and rotation at the end bearings. Lateral support may also be required at the interior bearings by the building code.
- 2 Girders are designed to be supported on the bottom edge only.
- 3 Multiple plies must be fastened together as per manufacturer's details.
- 4 Top loads must be supported equally by all plies.
- 5 Top must be laterally braced at end bearings.
- 6 Bottom must be laterally braced at end bearings.
- 7 Lateral slenderness ratio based on single ply width.

ID	Load Type	Location	Trib Width	Side	Dead 0.9	Live 1	Snow 1.15	Wind 1.6	Const. 1.25	Comments	
1	Uniform		1-0-0	Тор	10 PSF	40 PSF	0 PSF	0 PSF	0 PSF	Floor	
	Self Weight				11 PLF						

Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

- Dry service conditions, unless noted otherwise
 LVL not to be treated with fire retardant or corrosive
- Handling & Installation
- Infoculing & Installation

 I. VIL beams must not be cut or drilled

 Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beam strength values, and code approvals

 Damaged Beams must not be used

 Design assumes top edge is laterally restrained

 Design assumes top edge is laterally restrained is provide lateral support at bearing points to avoid lateral displacement and rotation

- 6. For flat roofs provide proper drainage to prevent ponding

This design is valid until 11/3/2024

Metsä Wood 301 Merritt 7 Building, 2nd Floor Norwalk, CT 06851 (800) 622-5850 www.metsawood.com/us

Manufacturer Info

Comtech Comecn Reilly Road Industrial Park P.O. Box 40408, NO USA 28309 910-864-8787

Page 2 of 3







Client: Project: Address: Jay Norris

71 knight Rd.

Date: 6/1/2023

Input by:

Job Name: J0423-1877 Beams Project #: J0423-1877 Beams

3-Ply - PASSED 1.750" X 16.000" Kerto-S LVL FB1

Application:

Design Method:

Building Code:

Load Sharing:

Deck:

Floor


ASD


Yes

IBC/IRC 2015

Not Checked

_evel: Level





Page 3 of 3

Member Information

Type: Plies: 3 Moisture Condition: Dry Deflection LL: 480 Deflection TL: 240 Importance:

Normal - II

Temperature: Temp <= 100°F

Reactions UNPATTERNED Ib (Uplift)

Brg	Direction	Live	Dead	Snow	Wind	Const
1	Vertical	606	224	0	0	0
2	Vertical	606	224	0	0	0

Bearings

Bearing L	_ength	Dir.	Cap. Rea	act D/L lb	Total	Ld. Case	Ld. Comb.
1-SPF 3	3.500"	Vert	11%	224 / 606	830	L	D+L
2-SPF 3	3.500"	Vert	11%	224 / 606	830	L	D+L

Analysis Results

Analysis	Actual	Location	Allowed	Capacity	Comb.	Case
Moment	1406 ft-lb	3'9 3/4"	53922 ft-lb	0.026 (3%)	D+L	L
Unbraced	1406 ft-lb	3'9 3/4"	24535 ft-lb	0.057 (6%)	D+L	L
Shear	766 lb	1'7 1/2"	17920 lb	0.043 (4%)	D+L	L
LL Defl inch	0.004 (L/21181)	3'9 13/16"	0.180 (L/480)	0.023 (2%)	L	L
TL Defl inch	0.006 (L/15472)	3'9 13/16"	0.359 (L/240)	0.016 (2%)	D+L	L

Design Notes

- 1 Provide support to prevent lateral movement and rotation at the end bearings. Lateral support may also be required at the interior bearings by the building code.
- 2 Girders are designed to be supported on the bottom edge only.
- 3 Multiple plies must be fastened together as per manufacturer's details.
- 4 Top must be laterally braced at end bearings.

Uniform

- 5 Bottom must be laterally braced at end bearings.
- 6 Lateral slenderness ratio based on single ply width

o Lator	ai didiladifidad fatio badda dif di	ingle ply Width.								
ID	Load Type	Location	Trib Width	Side	Dead 0.9	Live 1	Snow 1.15	Wind 1.6	Const. 1.25	Comments

40 PLF

159 PLF

0 PLF

Near Face

Self Weight 19 PLF

1

Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

- Dry service conditions, unless noted otherwise
 LVL not to be treated with fire retardant or corrosive

Handling & Installation

- LVL beams must not be cut or drilled Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beam strength values, and code approvals Damaged Beams must not be used
 - Design assumes top edge is laterally restrained
 Provide lateral support at bearing points to avoid
 lateral displacement and rotation

6. For flat roofs provide proper drainage to prevent ponding

This design is valid until 11/3/2024

Metsä Wood 301 Merritt 7 Building, 2nd Floor Norwalk, CT 06851 (800) 622-5850 www.metsawood.com/us

Manufacturer Info

0 PLF

Comtech Comecn Reilly Road Industrial Park P.O. Box 40408, NO USA 28309 910-864-8787





0 PLF 2F4