of the survey as calculated by coordinates is 1: 10 area shown hereon was calculated by coordinates.

Witness my thank brid seal this 16TH day of JANUARY 2024.

CARO
SEAI I, MICHAEL P. GRIFFIN , certify that under my direction and supervision this map was drawn from an actual field survey, that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates. PB 2002 PG 89 HARNETT CO. REGISTRY SEAL L-3331 O SURVE KAN JOSHUA MCCORMICK \$ ERNESTINE STOKES DB 4165 PG 93 N 07°10'57" E 120.00 0.52 AC. BEATRICE BAILEY HILL DB 1540 PG 251 N 81°31'49" RAY BYRD ROAD50' PUBLIC R/W

SETBACKS

 FRONT
 35'

 REAR
 25'

 SIDE
 10'

 CORNER SIDE
 20'

CI R=50.00' L=41.15' S32°09'07"E 40.00'

THIS PROPERTY IS NOT LOCATED
IN THE 100 YEAR FLOOD ZONE.


LEGEND

EXISTING IRON PIPE FES FL
IRON PIPE SET WM W
RIGHT OF WAY CO CL
NOW OR FORMERLY FH FIR

EXISTING IRON STAKE

FLARED END SECTION
WATER METER
CLEAN OUT
FIRE HYDRANT

CATCH BASIN





GRIFFIN LAND SURVEYING, INC.

FIP

IPS

R/W N/F

DRAWN BY KDF	DATE 1/16/24
CHECKED <u>BY</u> MPG	SCAL <u>E</u> 1" = 40'

FOUNDATION SURVEY

SBM HOMES LLC

STOCKYARD ROAD ESTATES II

LOT 50 510 RAY BYRD ROAD LILLINGTON, N.C.

HARNETT COUNTY LILLINGTON TOWNSHIP