

۲ 919 773-1200 = ۶ 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com

February 26, 2024

Chuck Michno David Weekley Homes 1901 Harrison Avenue, Suite 200 Cary, NC 27513 Email: <u>cmichno@dwhomes.com</u>

Reference: Engineering Services Permit # SFD2401-0049 Serenity - Lot 127 395 Serenity Walk Parkway Fuquay-Varina, NC 27526 TE&D Project No.: 2401-020164

To Whom It May Concern;

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to observe the following items:

- 1. Observe the materials/conditions of the monoslab foundation bearing soils.
- 2. 3rd Party monoslab footing excavation and slab preparation observations.

The following conclusions and recommendations were noted:

- 1. The materials/condition of the monoslab foundation bearing soils were visually observed, qualitatively probed, and subjected to Static Cone Penetrometer (SCP) testing. Based on our observations and analysis, and providing that the monoslab footing soils have not been exposed to inclement weather after our site visit, the in-situ soils were noted as being adequate to support the anticipated loading conditions (2000 PSF).
- 2. The existing excavated monoslab footing and slab preparation was visually observed with regard to compliance with the project plans and applicable provisions of the 2018 North Carolina Residential Building Code. Based on our visual observations and analysis, the existing monoslab footing was prepared in general accordance with the project plans and applicable provisions of the 2018 North Carolina Residential Building Code.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely, Tyndall Engineering & Design

"A Amos

Tripp Amos PT III | 2401-020164

Prentice Tyndall Jr., P.E.





τ 919 773-1200 = p 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com





