





for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.























for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.



















Job	Truss	Truss Type	Qty	Ply	PBS\GUILFORD TRAD B RF CAFE
72418061	BA1L	Truss	1	4	Job Reference (optional)

UFP Mid Atlantic LLC, 5631 S. NC 62, Burlington, NC, Micah Clayton

Run: 8.73 S Jan 4 2024 Print: 8.730 S Jan 4 2024 MiTek Industries, Inc. Tue Jun 11 08:35:57 Page: 2 ID:x5f0wNbr6ly6jPGMcHs13qzA?K1-pXQr\_JZCuiKMeXzaQVIEZBkJ2b9SQuGDhV9Upbz7QRG

16) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.

17) Use MiTek JUS46 (With 4-16d nails into Girder & 4-16d nails into Truss) or equivalent spaced at 1-10-11 oc max. starting at 17-3-11 from the left end to

36-5-15 to connect truss(es) to front face of bottom chord.18) Fill all nail holes where hanger is in contact with lumber.

18) Fill all hall holes where hanger is in contact with lumber.

Hanger(s) or other connection device(s) shall be provided sufficient to support concentrated load(s) 9839 lb down and 1067 lb up at 32-11-12 on bottom chord. The design/selection of such connection device(s) is the responsibility of others.
Attic room checked for L/360 deflection.

## LOAD CASE(S) Standard

1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15

Uniform Loads (lb/ft)

Vert: 1-3=-40, 3-6=-40, 6-28=-40, 7-28=-280, 7-8=-287, 8-29=-280, 9-29=-40, 10-19=-13, 22-24=-7, 20-22=-7, 20-23=-7, 7-23=-7

Concentrated Loads (lb)

Vert: 31=-156 (F), 32=-156 (F), 33=-156 (F), 34=-156 (F), 35=-156 (F), 36=-156 (F), 37=-98 (F), 38=-98 (F), 39=-98 (F), 40=-159 (F), 41=-5210 (F), 42=-159 (F), 43=-98 (F), 44=-99 (F)







codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.







This besign is based upon parameters shown, and so an individual building Designer Sull verify all design information on this sheet for conformation and requirements of the specific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.



Job	Truss		Truss Type		Qty	P	Ply	PBS\GUILF(	ORD TR	RAD B	RF CAFE	
72418061	BF3L		Truss		1		2	Job Referen	ce (optio	onal)		
UFP Mid Atlantic LLC, 5631 S. N	IC 62, Bur	lington, NC, Micah Clay	ton	Run: 8.73 S	Jan 4 202	4 Prin	nt: 8.730 S	Jan 4 2024 Mi	Tek Indu	stries, I	Inc. Tue Jun 11 08:3	85:59 Page: 1
			<u>}</u>	3-6-6 3-6-6	7-2-4 3-7-14	1.5x3	3 <b>I</b> I			2100	a-unz rwinecpinoc	XXGuz TW9pebu027 QKE
			N-01-2 → 01-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-	8 <sup>12</sup> 3x5 = 2 W3 W2 B1 7 5 8 5x10 II	9	5x5=	4	7-10-2				
Plate Offsets (X, Y): [1]	0-1-12.0-1	-81	<u>}</u>	JUS26 JUS2 <u>3-6-6 J</u> 3-6-6 1	6 JUS2 <u>7-2-4</u> 3-7-14	:6 ──∤						
TCLL (roof) TCDL BCLL BCDL	(psf) 20.0 10.0 0.0* 10.0	Spacing Plate Grip DOL Lumber DOL Rep Stress Incr Code	2-0-0 1.15 1.15 NO IRC2015/TPI2014	CSI TC BC WB Matrix-MSH	0.25 \ 0.46 \ 0.32 H	DEFL /ert(LL /ert(CT lorz(C	-) -( T) -( T) (	in (loc) 0.01 4-5 0.02 4-5 0.00 4	l/defl >999 >999 n/a	L/d 240 180 n/a	PLATES MT20 Weight: 131 lb	<b>GRIP</b> 244/190 FT = 20%
LUMBER     BRA       TOP CHORD     2x4 SP No.2     TOF       BOT CHORD     2x6 SP No.2     BOT       WEBS     2x4 SP No.3     BOT       REACTIONS     (Ib/size)     4=1553/ Mechanical, (min. 0-1-8), 6=1247/0-3-8, (min. 0-1-8)       Max Horiz     6=285 (LC 5)     Max Horiz       Max Horiz     6=286 (LC 5)     Max Horiz					BRACING OP CHORI GOT CHORI	)	Stru ver Rig	uctural wood sh ticals. id ceiling direct	eathing c	directly d or 10-	applied or 6-0-0 oc 0-0 oc bracing.	purlins, except end
Max Carw 4-2052 (Lc 15), 6=1617 (LC 16) FORCES (b) Max. Comp.Max. Ten All forces 250 (b) or less except when shown. TOP CHORD 1-2=-1077/86, 1-3=-1329102 BOT CHORD 0-7=2591201, 5-7=-2592021, 5-8=-178/882, 4-9=-178/882, 4-9=-178/882 WEBS 2-5=-138/1505, 2-4=-1472/202, 1-5=- Top chords connected together with 01d (0.131*/27) nails as follows: Top chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. He bottom chords and yn 0-90 oc. He dot into low follows hepe heperies in contact with heperies in contact with humber. Juliow Lozds (lot) Wet: 7-3=00, 4=-20 Concentrated Lozds (lo) Wet: 7-3=00, 4=-20 Vet: 7-							ROLLAR RESELTION					

















_	-	
_	-	
	-	
	-	























for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.

















is responsibility of the Building Designer. Building Designer shall verify all design information on this sheet for conformance with conditions and requirements of the specific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.









for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.























for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.



















Job	Truss	Truss Type	Qty	Ply	PBS\GUILFORD TRAD B RF CAFE
72418061	BA1L	Truss	1	4	Job Reference (optional)

UFP Mid Atlantic LLC, 5631 S. NC 62, Burlington, NC, Micah Clayton

Run: 8.73 S Jan 4 2024 Print: 8.730 S Jan 4 2024 MiTek Industries, Inc. Tue Jun 11 08:35:57 Page: 2 ID:x5f0wNbr6ly6jPGMcHs13qzA?K1-pXQr\_JZCuiKMeXzaQVIEZBkJ2b9SQuGDhV9Upbz7QRG

16) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.

17) Use MiTek JUS46 (With 4-16d nails into Girder & 4-16d nails into Truss) or equivalent spaced at 1-10-11 oc max. starting at 17-3-11 from the left end to

36-5-15 to connect truss(es) to front face of bottom chord.18) Fill all nail holes where hanger is in contact with lumber.

18) Fill all hall holes where hanger is in contact with lumber.

Hanger(s) or other connection device(s) shall be provided sufficient to support concentrated load(s) 9839 lb down and 1067 lb up at 32-11-12 on bottom chord. The design/selection of such connection device(s) is the responsibility of others.
Attic room checked for L/360 deflection.

## LOAD CASE(S) Standard

1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15

Uniform Loads (lb/ft)

Vert: 1-3=-40, 3-6=-40, 6-28=-40, 7-28=-280, 7-8=-287, 8-29=-280, 9-29=-40, 10-19=-13, 22-24=-7, 20-22=-7, 20-23=-7, 7-23=-7

Concentrated Loads (lb)

Vert: 31=-156 (F), 32=-156 (F), 33=-156 (F), 34=-156 (F), 35=-156 (F), 36=-156 (F), 37=-98 (F), 38=-98 (F), 39=-98 (F), 40=-159 (F), 41=-5210 (F), 42=-159 (F), 43=-98 (F), 44=-99 (F)







codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.







This besign is based upon parameters shown, and not an individual building Designer Shall verify all design information on this sheet for conformation and requirements of the specific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.



Job	Truss		Truss Type		Qty	P	Ply	PBS\GUILF(	ORD TR	RAD B	RF CAFE	
72418061	BF3L		Truss		1		2	Job Referen	ce (optio	onal)		
UFP Mid Atlantic LLC, 5631 S. N	IC 62, Bur	lington, NC, Micah Clay	ton	Run: 8.73 S	Jan 4 202	4 Prin	nt: 8.730 S	Jan 4 2024 Mi	Tek Indu	stries, I	Inc. Tue Jun 11 08:3	85:59 Page: 1
			<u>}</u>	3-6-6 3-6-6	7-2-4 3-7-14	1.5x3	3 <b>I</b> I			2100	a-unz r wneepmoe	XXGuz TW9pebu027 QKE
			N-01-2 → 01-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-	8 <sup>12</sup> 3x5 = 2 W3 W2 B1 7 5 8 5x10 II	9	5x5=	4	7-10-2				
Plate Offsets (X, Y): [1]	0-1-12.0-1	-81	<u>}</u>	JUS26 JUS2 <u>3-6-6 J</u> 3-6-6 1	6 JUS2 <u>7-2-4</u> 3-7-14	:6 ──∤						
TCLL (roof) TCDL BCLL BCDL	(psf) 20.0 10.0 0.0* 10.0	Spacing Plate Grip DOL Lumber DOL Rep Stress Incr Code	2-0-0 1.15 1.15 NO IRC2015/TPI2014	CSI TC BC WB Matrix-MSH	0.25 \ 0.46 \ 0.32 H	DEFL /ert(LL /ert(CT lorz(C	-) -( T) -( T) (	in (loc) 0.01 4-5 0.02 4-5 0.00 4	l/defl >999 >999 n/a	L/d 240 180 n/a	PLATES MT20 Weight: 131 lb	<b>GRIP</b> 244/190 FT = 20%
LUMBER     BR/       TOP CHORD     2x4 SP No.2     TOF       BOT CHORD     2x6 SP No.2     TOF       WEBS     2x4 SP No.3     BOT       REACTIONS     (Ib/size)     4=1553/ Mechanical, (min. 0-1-8), 6=1247/0-3-8, (min. 0-1-8)       Max Horiz     6=285 (LC 5)     Max Horiz       Max Horiz     6=285 (LC 5)     Max Horiz					BRACING OP CHORI GOT CHORI	)	Stru ver Rig	uctural wood sh ticals. id ceiling direct	eathing c	directly d or 10-	applied or 6-0-0 oc 0-0 oc bracing.	purlins, except end
Max Carw 4-2052 (Lc 15), 6=1617 (LC 16) FORCES (b) Max. Comp.Max. Ten All forces 250 (b) or less except when shown. TOP CHORD 1-2=-1077/86, 1-3=-1329102 BOT CHORD 0-7=2591201, 5-7=-2592021, 5-8=-178/882, 4-9=-178/882, 4-9=-178/882 WEBS 2-5=-138/1505, 2-4=-1472/202, 1-5=- Top chords connected together with 01d (0.131*/27) nails as follows: Top chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Bottom chords connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-9-0 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. Web connected as follows: 2x4 - 1 row at 0-90 oc. He bottom chords and yn 0-90 oc. He dot into low follows hepe heperies in contact with heperies in contact with humber. Juliow Lozds (lot) Wet: 7-3=00, 4=-20 Concentrated Lozds (lo) Wet: 7-3=00, 4=-20 Vet: 7-							ROLLAR RESELTION					

















_	-	
_	-	
	-	
	-	























for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.

















is responsibility of the Building Designer. Building Designer shall verify all design information on this sheet for conformance with conditions and requirements of the specific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.

