


System: Pressure Manifold  
 Lines: 5-7, (290')  
 Accepted Status System  
 0.35 Soil LTAR  
 22" Trench Bottom

Repair: Pressure Manifold  
 Lines: 1-4, (215')  
 T&J Panel 50% Reduction  
 0.35 Soil LTAR  
 22" Trench Bottom

- \*Keep tanks and drain lines 10' from property lines.
- \*Not a survey.
- \*Not a guarantee of a septic permit.
- \*Keep supply lines >5' from property lines.
- \*Some lines are flagged longer in the field than lengths indicate.
- \*No grading septic area.



Central Carolina Soil Consulting, PLLC  
 1900 South Main Street, Suite 110  
 Wake Forest, North Carolina 27587  
 Phone (919)569-6704 Fax (919)569-6703

3-Bedroom Septic Layout  
 Lot 159, Birchwood Subdivision  
 Harnette County, North Carolina

|                   |
|-------------------|
| Job# : 3753       |
| Drawn By : LW     |
| Date : 04/12/2023 |
| Revision:         |
|                   |
|                   |