

April 16th, 2024

Edward & Mary Green  
160 Eastmill Lane  
Holly Springs, NC 27540

**Re: Status of Permit Application-SFD2404-0002**

**To whom it may concern,**

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Use pink flags to mark property lines and irons that are Set by surveyor need to be visible. (\$25.00 Fee incurred)
- 2. House Box needs to be marked to match site plan (\$25.00 Fee Incurred)
- 3. Directions not clear to property (\$25.00 fee incurred)
- 4. Property needs undergrowth cleared, do not disturb the soil
- 5. Driveway not shown on site plan
- 6. Backhoe pits required – Call office between 8-9am on the day you are going to dig pits to see availability. There are 8 locations marked with white environmental health flags where pits are needed. Pits will need to be 4' deep (48"). Wide enough to get into, and must have a step to get out of pits. Do not dig pits when rain is expected.**
- 7. Other –

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7525 ext. 2 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Reynold Levocz R.E.H.S.  
Environmental Health Specialist  
Harnett County Department of Public Health

RL/kh  
Copy: Central Permitting