

www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

ph: 910-893-7550

fax: 910-893-9429

May 22nd, 2024

Fausto Santiago 8324 Oakcliff Lane Angier, NC 27501

Re: Status of Permit Application-SFD2405-0009

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

| 1. Use pink flags to mark property lines flagged every 50' and irons that are set by surveyor need to be visible. Need front right property corner irons uncovered and demonstrated. (\$25.00 Fee incurred) |
|--|
| 2. House Box needs to be marked to match site plan (\$25.00 Fee Incurred) |
| 3. Directions not clear to property (\$25.00 fee incurred) |
| 4. Property needs undergrowth cleared, do not disturb the soil |
| 5. Driveway not shown on site plan |
| 6. Backhoe Pits Required |
| X_7. Other – House box must be moved towards the left property line as close as possible (as if standing on Tyree Lane). This will provide adequate room for a septic system. A survey map must be submitted with property line measurements and desired drive way from Tyree Lane to the house box. |

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7525 ext. 2 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Ru fu REHS

Reynold Levocz R.E.H.S.

Environmental Health Specialist

Harnett County Department of Public Health

RI /kh

Copy: Central Permitting

strong roots · new growth