

Howerton Services, PLLC
License # P-1716
3513 Cathedral Bell Road
Raleigh, NC 27614
(919) 270-3460

May 28, 2025

Subject: 15 Bourbon Street
Fuquay Varina, NC 27526
Plan Revision Letter
Harnett County Permit #: SFD2503-0103

Based on the request of the Contractor, 1 item was modified in the approved plans. My assessment and recommendations are as follows:

- Item 1: There is a double 2x10 Hip Beam shown in the Roof Plan at the front left section of the home. The bottom portion of the Hip Beam is not required. Only the short section of the Hip beam over the double 2x10 valley beam and the 2x10 ridge beam will be installed. The Contractor installed a double rafter on the opposing side of the double 2x10 valley at the ridge beam.

The 1 item noted above meets all the requirements of the 2018 North Carolina Building Code for Residences.



05 28 2025 EDT