

Date: 10/17/2025

To: **David Gibson**
Davidson Homes
1903 N. Harrison Avenue
Cary, NC 27513
dgibson@davidsonhomesllc.com
919-356-4401

Re: Slab Repair Verification
Location: Lot 43 Retreat at North Main (233 Tenure Ln. Buies Creek NC)
JDS Project No.: RDU2510749
Date of Inspection: 10/17/25

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

Observations

The client requests an evaluation of the Slab excavations at the pantry door wall, and the rear of the kitchen island.

Recommendations

Based on our on-site observations and review, the client has followed the recommendations set forth in the previous letter RDU2510509, the client may proceed with the placement of a minimum of 3000 PSI concrete.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 984-344-4691.

Respectfully Submitted,
Patrick Ruff



Reviewing Engineer:
Maxwell C. Danskin, PE

