



www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

> ph: 910-893-7550 fax: 910-893-9429

September 18th, 2025

LGI Homes 1450 Lake Robbins Dr The Woodlands, TX 77380

Re: Status of Permit Application-SFD2509-0004

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

1. Survey Corner Irons need to be uncovered and clearly demonstrated. Property lines need to be reflagged/marked every 50' between survey irons. (25.00 Fee Incurred)
_2. House Box needs to be marked/demonstrated clearly. (25.00 Fee Incurred)
3. Directions not clear to property (\$25.00 fee incurred)

__4. Needs more clearing. Do not disturb the soil.

____5. Driveway not shown on site plan

X 6. Backhoe Pits Required

7. Other-.

Your application will be put on hold until the selected items above have been addressed. **Please call 910-893-7547 to schedule** your property for evaluation.

Sincerely,

Mark Osborne R.E.H.S.

Environmental Health Specialist

MO/kh

Copy: Central Permitting