

www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

> ph: 910-893-7550 fax: 910-893-9429

Oct 20th, 2025

Value Build 3015 Jefferson Davis Hwy Sanford, NC 27332

Re: Status of Permit Application-SFD2509-0052

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

X_1. Survey Corner Irons need to be uncovered and clearly demonstrated. (25.00 Fee Incurred)
_2. House Box needs to be marked/demonstrated clearly. (25.00 Fee Incurred)
_3. Directions not clear to property (\$25.00 fee incurred)
_4. Needs more clearing. Do not disturb the soil.
_5. Driveway not shown on site plan
_6. Backhoe Pits Required
_7. Other-

Your application will be put on hold until the selected items above have been addressed. **Please call 910-893-7525 to schedule** your property for evaluation.

Sincerely,

Mark Osborne R.E.H.S.

Environmental Health Specialist

MO/kh

Copy: Central Permitting