

November 5th, 2025

Premier Carolina Homes LLC
142 Northfield Rd
Statesville, NC 28625

Harnett County Government Complex
307 W. Cornelius Harnett Boulevard
Lillington, NC 27546

ph: 910-893-7550
fax: 910-893-9429

Re: Status of Permit Application-SFD2510-0083

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

X 1. Survey Corner Irons need to be uncovered and clearly demonstrated. Have surveyor flag/mark every 50' between property survey corner irons. (25.00 Fee Incurred)

- 2. House Box needs to be marked/demonstrated clearly. (25.00 Fee Incurred)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Needs more clearing. Do not disturb the soil.
- 5. Driveway not shown on site plan
- 6. Backhoe Pits Required

X 7. Other- Site plan house box setback measurements are not accurate as demonstrated onsite, must fix house box onsite.

Your application will be put on hold until the selected items above have been addressed.
Please call 910-893-7525 to schedule your property for evaluation.

Sincerely,



Reynold Levocz
Environmental Health Specialist
RL/kh
Copy: Central Permitting