



For side-loaded multiple member beams, additional nailing or bolting may be required. See current Joist literature.



REV	BY	DATE / DESC.
SD	JDS	6/19/25

DESIGN DATA

die
tp
NC
PAGE NO.
AC 2278
1-20
1989

--	--	--	--

DRAWN BY: TJF DATE: 11/4/25

SCALE: $1/4" = 1'-0"$