COMPLAINT

Andrew Currin

From:

Core.Concepts.office <Core.Concepts.office@protonmail.com>

Sent:

Sunday, April 11, 2021 6:11 PM

To:

Andrew Currin; Joe Temple, (landlord)

Subject:

Spetic Issues at 192 Joseph Alexander Dr

Attachments:

2021-04-08_092957.jpg

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Andrew

Attached is a copy of the invoice from the lisenced septic contractor who fixed the pump.

We had the pump replaced a few years ago and attempted to hold the sub who did the work then to honoring the waranty. He refused and we hirred Larry to do th ework.

His invoice with lisence number is attached.

Please feel free to stop by anytime, some one is almost always here and can show you where the septic is. If you come by and one of the kids of my wife does not under stand where something is..

the spetic is no the rigth side rear. the solids tank is about 10 feet behind th house and 10 feet to right of deck. There is a clean out by the house under the window that will help locate it. The rest is seen from the surface.

Not sure what else yo may need ut feel free to stop by or call me. I am not the owner, I am the tenant, but i am a GC and can resolve most issues.

thanks and have a great day!

Love never fails!

John Foy 910 890 8973 NC Independent Adjuster NC General Contractor

Sent with ProtonMail Secure Email.

989239

| MACCHART | SINDL STATES | SOUTH OF MENTS OF THE SOUTH OF |
|----------|---|---|
| 505505 | miles 100 miles | M. S. Lighter |
| ~ CEOZ | Le golles | t us rostes oftend oftend |
| der Da. | La Delegan | trop 16/ |