

MGB 2000 LLC
2434 Pepperstone Drive
Graham, NC 27253



CERTIFICATION OF FINAL VISUAL INSPECTION

SHAW TOWN ELKIN COUNTY

PROJECT: 695 SHAWTOWN RD LILLINGTON NC

WORK AREA: EAST WING CLASSROOM HALLWAY

CONTRACTOR CERTIFICATION

In accordance with project specifications the Contractor hereby certifies that all asbestos materials required to be removed are gone, and that he has visually inspected the entire work area (all surfaces including pipes, beams, ledges, walls, ceiling and floor, decontamination unit, sheet plastic, etc.) and has found no dust, debris or residue that might be suspect for asbestos.

by: (Signature) [Signature] Date: 9-21-18

(Print Name) JERRY PATRICK

(Print Title) SUPERVISOR

PROJECT INSPECTOR CERTIFICATION

The Project Inspector hereby certifies that he has personally conducted a visual inspection and verifies that this inspection has been thorough and, to the best of his knowledge and belief, the Contractor's certification above is a true and honest one.

by: (Signature) [Signature] Date: 9-21-18 Time: 1:25

(Print Name) MICHAEL G. BOLLARD

Certification: AIR MONITOR No. PC026 Exp. 1-19

Comments: removal floor tile mortar
classroom & hallway

Continued on back Y N