

909 E. Elm St Graham, NC 919-630-8419

Date:

10/26/2018

Summary Report for Asbestos Containing Materials

<u>Client</u>
Michael J. Brown, P.G. President
TERRAQUEST ENVIRONMENTAL CONSULTANTS, P.C.
100 East Ruffin St.
Mebane, NC 27302

Site Name & Address Alkins Grocery 359 NC-24 Cameron, NC.

Zava Industrial, Inc. (Zava) is pleased to provide this summary report documenting Asbestos Containing Building Materials, (ASBM) for the metal canopy which is planned for demolition. The canopy is approximately 24' x 24' held up by two 8" x8" steel poles. Canopy color is white with a faded blue and red strip around the edge. After inspection of canopy, no suspect materials were found on canopy and no lab report issued with this summary.

Thank you for allowing us to be of service to you. If you have any questions, please contact us at (919) 630-8419.

Accredited-Asbestos Inspector John Maynard #13262

Asbestos is a group of six naturally occurring minerals composed of soft, flexible fibers that are heat-resistant.

Asbestos is still used in hundreds of U.S. consumer products. Its use is allowed as long as it accounts for less than 1% of the product. Exposure to asbestos causes cancers and other diseases, including mesothelioma and aspestosis.

www.asbestos.com







