



Strength Test Results

Client: TM Engineering, Inc.
Project: Lakeside Storage / Angier, NC
Job No: 1260593CA
Client Job No:

Date Cast: 7/17/2026
Lab No: 57792
Mix No: 3000
Design Strength: 3000

Field Information

Date Received in Lab:	7/18/2026	Water:	Physical Tests		
Sampled by:	TME	Authorized by:	Slump (in):	7.25	Specified:
Concrete Supplier:	Concrete Service	Temperature: Air 88°F Sample 82°F	Air Content (%):	1.00	Specified:
Plant Location:	15	Size of Load (cy): 10.0	Unit Weight (pcf):	143.5	
Truck No: 6008	Ticket #: 1520958	Specified Strength (28 days): 3000	HI:		LO:
Time: Mixed 05:35 AM	Sampled 06:00 AM				

Location of Placement: Building 2

Field Remarks:

Core	Test Date	Age (days)	Load (lbs)	Diameter (in)	Area (in²)	Strength (psi)	Corr. Factor	Fracture Type
A	7/24/2026	7	31,877	4.00	12.57	2,540	1.00	2
B	8/14/2026	28	39,200	3.98	12.44	3,150	1.00	2
C	8/14/2026	28	42,100	3.98	12.44	3,380	1.00	2
D	8/14/2026	28	41,100	3.98	12.44	3,300	1.00	2
E	8/14/2026	28	41,600	3.98	12.44	3,340	1.00	2

* = Less than design strength

Strength testing performed by: Tyler Littmann

Notes: Strength tests performed in accordance with ASTM C-39.

Distribution: Ashley Mallik, David Truesdale, Laurel Ramsey, Project Management

This report shall not be reproduced, except in full, without the prior written approval of GeoTechnologies, Inc. These results relate only to the items inspected or tested.

Michael K. Morton

Submitted by

Report Date 8/16/2026

Signature