



Inspection Report - Passed

Facility Information

Occupant Name: Fairview Pointe Village

Date 04/01/2025

Completed:

Street Number: 200

Building Class R2 -

Code: Apartments
, Non-
transient

City: Spring Lake

Street Name: Gallery

Postal Code: 29390

Street Type: Drive

State: NC


**Building 2
Number:**

Inspection Information

Inspection Type: 303.3-Underground Piping, Flush Test

Inspection Inspection
Results: Passed

Signatures

Type	First Name	Last Name	Signature Date	Signature Graphic
Inspector	Roger	Sullivan	04/01/2025	

Inspection Notes

Witnessed flush test on sprinkler main, all passed.

Permit Information

Was operational No
permit Issued?:

Inspection Results: Inspection Passed