

# Wayne R. Dashfield, PE

421-B South Bright Leaf Blvd. Smithfield, NC 27577

(919) 934-0961

March 22, 2022

Re: Solid Rock Facility  
1267 Steward Road  
Dunn, NC.

Subject: Third Party Inspection

Dear Sir, Madam:

On March 21, 2022 I made an on-site visit to the proposed Solid Rock Facility located at 1267 Steward Road in Dunn, NC. The purpose of this visit was to act as a third party inspection for the Harnett County Inspections. This visit involved the inspection of the foundation for the proposed concrete pour and the placement of the reinforcing steel for the 50'x190' pad.

Based on my inspection there were (8) F-1 with hair pin rebar and (8) F-2 footings. All of the rebar for the footing and foundation are #5 rebar. The 6x6 steel mat and anchor bolts were installed. The size and number, placement of rebar and sizing of the footing were all installed in accordance to the approved plans.

Attached are the density and soil bearing test for this visit. If I can be of any more assistance, please feel free to contact me.

Yours truly,

Wayne R. Dashfield, PE

