


FIELD REPORT

Project Name: 94 Lunker Lane	Location: Holly Springs, NC
Project No.: 73747	Permit No.:
Client: Triangle Home Pros	Weather: Clear
Contractor: Triangle Home Pros	Date: 7/9/25
Technician: Dylan Rappleyea	Portal to Portal Time: 2.0


Summary: Rebar check for building pad

Notes: Timmons arrived on site as requested by contractor. Upon arrival, tech was informed that a rebar check was needed for the building pad below. Tech observed rebar that was placed and determined that it met site specifications for number, size, was properly supported and tied at connection points. Vapor barrier and steel grid was in place also. Tech left.



LIFE SAFETY PLAN BUILDING "1"
SCALE 1/8" = 1'-0"



Report By:  (Signature) Dylan Rappleyea (Print)

Reviewed By: George Nicksich **Date:** 7/9/25

Page 1 of 1