



NOTES:
 F = FRAME TIE
 X = CROSS TIE
 LS = LONGITUDINAL STRAP

FIELD INSPECTION REPORT	
CLAYTON HOMES	
388 TURLINGTON RD., DUNN, NC	
DATE	DWG. NO.
11/11/19	
SHEET NO.	
2 OF 2	