

October 26, 2018

Clayton Homes of Sanford
194 Keller Andrews Road
Sanford, NC 27330

**RE: Existing Septic System Inspection BRES 1810-0043
88 Luke Road**

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

1. Uncover outlet lid on septic tank and break seal (\$25.00 fee incurred) see below

2. Have system pumped out

3. Replace sanitary T

4. Other - Tank not uncovered. Uncover outlet end of septic tank and break seal of lid free. Reconfirm with Environmental Health when inspection is ready.

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S.
Environmental Health OSWW Specialist
Harnett County Department of Public Health
Environmental Health

AC/sgs
Copy - Central Permitting