

HTE #: BRES1902-0010

HARNETT COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH
307 CORNELIUS HARNETT BOULEVARD
LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Lucia Estudilla Vazquez

Phone #: 919.902.2265

Address: 815 Bailey Road Coats, NC 27521

Name of Mobile Home Park or S/D: _____

Name of Owner (if different): Marisol Barrientos Estudilla

Address of Owner (if different): 698 Church Road Benson, NC 27504

Property Location (State Road name and #): 815 Bailey Road (SR 1561)

Purpose of Inspection: 28'x44' DWMH 3 Bedrooms

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

1. the intended use of the septic system should change, and/or
2. the system should fail or malfunction, and/or
3. the owner or tenant of the property change, and/or
4. after six months

**BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM
DO NOT DRIVE OR PARK ON SEPTIC SYSTEM**

AUTHORIZATION OF EXISTING SYSTEM



Signature of Environmental Health Specialist

02/20/2019

Date