HTE# BILES 1907-0025

HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

	oranio del mo	STSTEM INSP	ECTION
NAME HATTUA	Lubenes		PHONE #
ADDRESS			
NAME OF MOBILE HO	ME PARK OR S/D	Wyndon	PIACE LOT
NAME OF OWNER (IF		/	
ADDRESS OF OWNER	(IF DIFFERENT) _		
PROPERTY LOCATION	N: STATE ROAD NA	AME AND # <u>5~/</u>	415 RAWS CHUCCH RD
Environmental Health	Section. At the time . If this system sho	of inspection, th	t County Health Department nere appeared to be a septic the owner is responsible for
THIS INSPECTION IS V (1) the intended use of the (2) the system should fail (3) the owner or tenant of (4) after six months	septic system should or malfunction, and/	l change, and/or	- 1 22X12 PAIT WILL BE COYERED
BUILDING MU DO NO	ST BE 5' FROM A	ANY PART OF RK ON SEPTIC	SEPTIC SYSTEM SYSTEM
AU	THORIZATION O		stratus stranomic acamemic sun acamemic sun security. STEM
James 2 1	(Ashant) sor	2 RGHS	3-3-20
Signature of Inspector			Data