Joe E. Godwin Sr., P.E., P.L.S.

Consulting Engineers & Surveyors

Phone: (919) 894-5731 (919) 894-7765 Fax: (919) 894-8190

Fleet Temple, P.E.

1403 NC Highway 50 South Benson, North Carolina 27504 Jason E. Godwin, P.L.S.

Email: general@enochengineers.com

November 6, 2019

Godwin Construction and Development P.O. Box 1922 Dunn, North Carolina 28335

ATTN: Mr. Buck Godwin

RE: Footing Inspection

Subject:

New Construction-Permit No. BRES 1908-0026

Detached barn

1510 Erwin Chapel Road

Dunn, NC 28334

To Whom It May Concern:

Our office performed an onsite inspection of detached structure's footings at the above subject site November 6, 2019. Soft or yielding areas were not present during the inspection of the footings. The footings were undercut in virgin and suitable fill material. The soil inspected has a minimum allowable bearing capacity of 2,000 lb/ft². In addition, the footing depth, width and rebar placement were constructed in accordance with Michael Synott, PE sealed plans for owners, "Charles and Paula Bradshaw". If we may be of further assistance, please feel free to call.

Respectfully,

Joe E Godwin Sr., P.E. Enoch Engineers, P.A.

JEG Sr. / jeg