Application/Permit No.	
Pursuant to NCGS 153A-352 (C1, 2, 3 D),	
MICHAEL CAVNAR have	
personally (or had an agent under my direct supervision) performed an	
inspection of the work done at the following location address:	
683 ADCOCK ROAD, LILLINGTON, N.C. 27546	
Scope of work was: REWORK. I.) NEW STAIRS BUILT WITH NO LANDING'S, STRAIGHT STAIR FOR MORE HEAD ROOM ON SECOND FLOOR. 2.) EDOZY ADDED TO ALL CRACKS IN MASSINY GROUTLING. 1.) NEW FRONT DOOR HEADER FOR DOUBLE DOORS. 4.) FLOOR SYSTEM FOR SECOND STORY, IS SUPPORTED BY INTERIOR WALLS, AND PERIMETER BLICK WIN	OUT AND RS TO ALLOW FS.
THIS WAS A STRUCTURAL INSpectION ONLY! NO TRADES HAVE BEEN INSPECTED BY THE	
I hereby certify that the work done meets all aspects of the North	
Carolina Building and technical codes in effect at the time of my	
inspection.	
Signature Michael Carmar Date 10/3/19	
Seal Here # 026912	
EL SEAN STENEY	
THE PROPERTY OF THE PARTY OF TH	
GINEER	
A. CAMINITATION OF THE PARTY OF	