



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

5/10/2021

SUBJECT: BRES1909-0058
BUILDING RESIDENTIAL

To: GRANDY LISA LEIGH

Here are the results of all Inspections located at **539 VALLEY RD:**

Inspection Type: FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: ZONING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Planning Bucket
Result:
Remarks:
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 5/5/2021
Completed Date/Time: 5/5/2021
Inspector: GIS Bucket
Result: APPROVED
Remarks:
Notes: 539 VALLEY RD SPRING LAKE 28390.

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 5/10/2021
Completed Date/Time: 5/10/2021
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks:
Notes: would like an inspection after 12 please. she works at the schools.
Unable to verify exterior connections due to being covered, seal around water distribution line where it enters foundation, address needs to be visible from road