

Harnett County 108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

3/9/2021

SUBJECT: **BRES1912-0002**

BUILDING RESIDENTIAL

To: MCLEAN BEVERLY ANN

Here are the results of all Inspections located at 50 RUSS DR:

Inspection Type: FOOTING

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: FOUNDATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: INSULATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: MONO SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:



Harnett County

108 EAST FRONT STREET

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: ROUGH IN

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: TAX INSPECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Tax Inspection

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:



Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 1/8/2020
Completed Date/Time: 1/8/2020
Inspector: Steven Gazlay
Result: DISAPPROVED

Remarks:

Notes:

Floor joists in kitchen area do not meet span. Contractor to place drop girder to correct. Ok to

insulate. Schedule insulation and rough in inspections together.

Inspection Type: FINAL**
Scheduled Date/Time: 4/1/2020
Completed Date/Time: 4/1/2020
Inspector: Deen Taylor
Result: DISAPPROVED

Remarks:

Notes:

Steven Gazlay
OPEN FLOOR

Jim Hartman, said the inspector said he could finish the job and all of tis could be seen a the

final.

Floor joists in kitchen area do not meet span. Contractor to place drop girder to correct. Ok to

insulate. Schedule insulation and rough in inspections together.

Contractor stated drop girder was added along with for peers and footers but we're not inspected. Engineer letter required to state that new peers and footings were installed per

residential code

Inspection Type: FINAL**
Scheduled Date/Time: 6/17/2020
Completed Date/Time: 6/17/2020
Inspector: Deen Taylor
Result: APPROVED

Remarks:

Notes: engineer letter is in attachment. If you need access to site please call Jim Hartman 910-263-

3829

