

HTE# BRES-2003-0031

HARNETT COUNTY HEALTH DEPARTMENT  
ENVIRONMENTAL HEALTH  
307 CORNELIUS HARNETT BOULEVARD  
LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

NAME: Michael ORTIZ PHONE # 919-903 6146

ADDRESS 89 Kenton Drive F.V. N.C. 27526

NAME OF MOBILE HOME PARK OR S/D Oliver Branch lot 7

NAME OF OWNER (IF DIFFERENT) Lisa A Vresti

ADDRESS OF OWNER (IF DIFFERENT) 89 Kenton Dr F.V. N.C. 27526

PROPERTY LOCATION: STATE ROAD NAME AND # 52 Oliver Branch RD

PURPOSE OF INSPECTION: 30X30 Attached Garage Only

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If this system should malfunction, the owner is responsible for any necessary repairs.

- THIS INSPECTION IS VOID IF:
- (1) the intended use of the septic system should change, and/or
  - (2) the system should fail or malfunction, and/or
  - (3) the owner or tenant of the property changes, and/or
  - (4) after six months

**BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM  
DO NOT DRIVE OR PARK ON SEPTIC SYSTEM**

AUTHORIZATION OF EXISTING SYSTEM

James E. Markham JR RSHS  
Signature of Environmental Health Specialist

3-24-20  
Date