HARNETT COUNTY HEALTH DEPARTMENT **ENVIRONMENTAL HEALTH** 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Jose R. Santiago

Phone #: 910.658.6400

Address: 136 Curtis Dr. Erwin, NC 28339

Name of Mobile Home Park or S/D: Kennedy Acres Lot 13

Name of Owner (if different): Same

Address of Owner (if different): Same

Property Location (State Road name and #): 136 Curtis Dr.

Purpose of Inspection: 30'x36' Det. Garage

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

- 1. the intended use of the septic system should change, and/or
- 2. the system should fail or malfunction, and/or
- 3. the owner or tenant of the property change, and/or
- 4. after six months

BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

AUTHORIZATION OF EXISTING SYSTEM

Signature of Environmental Health Specialist