



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

4/2/2020

SUBJECT: BRES2003-0042
BUILDING RESIDENTIAL

To: Montey Pelto

Here are the results of all Inspections located at **12 SADDLETREE DR:**

Inspection Type: FOOTING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 3/18/2020
Completed Date/Time: 3/18/2020
Inspector: GIS Bucket
Result: APPROVED
Remarks:
Notes: 12 SADDLETREE DR SPRING LAKE 28390.





Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 3/18/2020
Completed Date/Time: 3/18/2020
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks:
Notes:

Inspection Type: TAX INSPECTION
Scheduled Date/Time: 3/20/2020
Completed Date/Time: 3/26/2020
Inspector: Tax Inspection
Result: APPROVED
Remarks:
Notes: SW IN MHP - TO BE ASSESSED AS PP FOR 2021 -

Inspection Type: ZONING
Scheduled Date/Time: 3/23/2020
Completed Date/Time: 3/23/2020 2:00 PM
Inspector: Randy Baker
Result: APPROVED
Remarks:
Notes:

Inspection Type: MFH FINAL**
Scheduled Date/Time: 3/27/2020
Completed Date/Time: 3/27/2020
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks:
Notes: Unable to verify sewer connection due to being covered. Address on MFH says 28

Inspection Type: MFH FINAL**
Scheduled Date/Time: 4/1/2020
Completed Date/Time: 4/1/2020
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks:
Notes: