HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: James Clemons	Phone #:	919-356-358
Address: 54 Clemons Ln, Sanford		
Name of Mobile Home Park or S/D:		
Name of Owner (if different):	-	
Address of Owner (if different): 128	Clemons	Ln, Sanford
Property Location (State Road name	and #): <u>S</u>	R# 1204
Purpose of Inspection: 28'x76' 4 bed	room DW	МН

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

- 1. the intended use of the septic system should change, and/or
- 2. the system should fail or malfunction, and/or
- 3. the owner or tenant of the property change, and/or
- 4. after six months

BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

AUTHORIZATION OF EXISTING SYSTEM

Signature of Environmental Health Specialist