Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Evalua	ed Facility: { on of Site: { Supply: tion Method: f Wastewate	Applicant WH ATWER B Auger T:	Date In Date In Date In Design Sewage	Evaluated: 77 7 n Flow (.1949): 31 rty Recorded: dividual	Cut	ze:	ner		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Consistence Texture Mineralogy		OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944 Wetness/ Soil Sapro Restr Color Depth (IN.) Class Horiz				Profile Class & LTAR
1,2	4_25%	0-48	GR LS	VFR SEXP	nsnp	48"			5 6.8
3,4	LZ51	0-48	GR SL	VFR SEXP	MOD	48"			8.6
			• 19 4-						
					1 22	, v =	¥		
							w.	110	
				~					
				1					
				-					

Description	Initial	Repair System	Other Factors (.1946):
3000 000 and 1000 and 1000	System		Site Classification (.1948):
Available Space (.1945)	V		Evaluated By: BA
System Type(s)	251, Red	251,800	Others Present:
Site LTAR	0.6	0.6	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE	I II	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE	Ш	SI-SILT SIL-SILT LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC
T-TERRACE FP-FLOOD PLAN		CL-CLAY LOAM SCL-SANDY CLAY LOAM			VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

